

Treadsafe Express

Instructions for Use



Ensure that the area to be coated is sound and free from oil, grease and loose material. If necessary, prepare the concrete with Concrete Etch. Non porous surfaces may be cleaned and degreased using Multi Clean. Any form of vegetation or mould may be removed by using Multi Wash. The substrate temperature should be between 10°C to 30°C for the application. Mechanically abrade the area to provide a key for the coating.

Remove all debris by sweeping and/or vacuum. Use masking tape to mark outer edges of coated area.

Empty activator into the base component container and mix with spatula or mechanical paddle for 5 minutes.

Apply one coat (at a rate not exceeding 10m² per 15kg kit and 5m² per 7 kg kit) to the substrate by brush or roller. Immediately blind with aggregate supplied.

Remove masking tape whilst coating is still wet.

After the coating has cured, remove excess aggregate with a soft brush.

Allow up to 24 hours for light traffic and up to 7 days for the full chemical cure.
For interior use.

TERO TECH Riverside Industrial Estate, Fazeley, Tamworth, Staffordshire, B78 3RW.
Head Office, Warehousing and Distribution: Tel: 01827 283322, Fax: 01827 250143. Telesales: 01270 611031

The **IM Group** utilizes a process of continuous product improvement for all of our products. While we do strictly adhere to our products' specifications, we routinely implement product improvements. Therefore, please contact us for our most current product specifications. IM Group warrants the quality of this product when used according to directions. User shall determine suitability of product for use and assumes all risk. The seller will not accept liability for more than product replacement.

Trademarks: **TECH TECH** is a registered trademark and subsidiary of **IM Group**.

